




3104

0.2-10

0-3

3104

3104

3104 = A00 +3104

3104 —

1 1997 20 130 100

2

3 1-8

0371-67898708

	3104
	F, O, H12, H14, H16, H18, H19, H22, H24, H26, H28, H111, H112, H114
mm	0.2-10
mm	100-2650

mm	C

0371-67898708

vip@hngymt.com

.



<https://www.hngymt.com/products/3104lj.html>